...IVIRONMENTAL PROTECTION (...C) REGION 10 1200 SIXTH AVENUE SEATTLE, WASHINGTON 98101



REPLY TO M/S ES-098

RECEIVED

JUL 12 093

DEM OF BUTTON

Ruth A. Nelson Associate General Council Marine Power & Equipment Inc. 1441 N. Northlake Way Seattle, Washington 98103

Dear Ms. Nelson:

On April 6, 1987, the EPA dive team investigated the Duwamish River bottom in the vicinity of the Marine Power and Equipment facilities. The purpose of the investigation was to determine the amount and extent of any sandblasting debris present there.

Over the entire area that the divers observed, only a light "dusting" of sandblasting grit was found on the river bottom near the west end of the syncro-lift and the dry dock. The areas underneath the syncro-lift and the dry dock were not investigated.

Given the small amount of sandblasting grit found during this particular survey, I don't believe that any removal of sandblasting debris, in this area, is necessary.

Sincerely,

Machael J. State

Michael F. Matta, Environmental Scientist Technical Support Branch

> USEPA SF 1260887